



# V54.17.x

## Summary of Firmware Changes

---

This document summarizes the following V54.16.x firmware releases:

Firmware Release Number	Release Date	See Page
<i>V54.17.14Z</i>	09 April 2014	page 1
<i>V54.17.12Z</i>	28 August 2012	page 2
<i>V54.16.3ZA</i>	25 October 2010	page 2
<i>V54.16.3Z</i>	31 December 2009	page 3
<i>V54.16.2Z</i>	15 August 2009	page 3
<i>V54.16.1ZD</i>	26 May 2009	page 3
<i>V54.16.1ZC</i>	10 March 2009	page 4
<i>V54.16.1ZB</i>	12 January 2009	page 4
<i>V54.16.1Z</i>	09 May 2008	page 4

## V54.17.14Z

**Release Date: 09 April 2014**

This firmware release includes features of the previous V54.17.12Z release. It is for use with the following printer models:

- HC100

### Changes

- None.

### Issues Corrected

- Wristbands will no longer be intermittently be pulled back into the cartridge if the user installs a cartridge and then powers up.

## V54.17.12Z

**Release Date: 28 August 2012**

This firmware release includes features of the previous V54.16.3ZA release. It is for use with the following printer models:

- HC100

### Changes

- The HC100 Printer now supports print speeds of 4ips on specific media cartridges
- The HC100 Printer now supports a WLAN radio.

### Issues Corrected

- Printing is no longer interrupted when a print job using RTC rolls over to 00:00.
- The Datamatrix barcode is now more tolerant of data that uses spaces in the ^FD data.
- The printer will not reset when using ~HQPP or ~WQPP.
- *Invalid selection. Press Enter to continue* no longer appears when hitting Enter during a telnet (port 23) session.
- Print servers now properly handle fragmented TCP packets.

## V54.16.3ZA

**Release Date: 25 October 2010**

This firmware release includes features of the previous V54.16.3Z release. It is for use with the following printer models:

- HC100

### Changes

None.

### Issues Corrected

- The Print Server will now completely close a connection after a connection timeout.

## V54.16.3Z

**Release Date: 31 December 2009**

This firmware release includes features of the previous V54.16.2Z release. It is for use with the following printer models:

- HC100

### Changes

None.

### Issues Corrected

- Multiple connections being opened and closed at the same time will no longer cause labels to print out of order.

## V54.16.2Z

**Release Date: 15 August 2009**

This firmware release includes features of the previous V54.16.x release. It is for use with the following printer models:

- HC100

### Changes

- Firmware version number updated with no functional changes.

## V54.16.1ZD

**Release Date: 26 May 2009**

This firmware release includes features of the previous V54.16.x release. It is for use with the following printer models:

- HC100

### Issues Corrected

- The wired and wireless print servers will now close the connection when the Host resets a connection that does not contain any data.

## V54.16.1ZC

**Release Date: 10 March 2009**

This firmware release includes features of the previous V54.16.x release. It is for use with the following printer models:

- HC100

### Changes

- Autoexec files will now only run once the media cartridge has been inserted.

### Issues Corrected

- Improved media cartridge recognition.
- Unnecessary media movements will now not occur when a new media cartridge is loaded.

## V54.16.1ZB

**Release Date: 12 January 2009**

This firmware release includes features of the previous V54.16.x release. It is for use with the following printer models:

- HC100

### Issues Corrected

- The internal 10/100 Print Server now responds to TCP packets when sent at a high rate.
- The print server will remain on-line after a very high level of NetBIOS traffic.
- The print server will now respond correctly to LPQ Stat inquiries and LPD job control messages.
- The printer will now retain the default gateway address after a power cycle.
- Autoexec.zpl files are now processed correctly during start up.

## V54.16.1Z

**Release Date: 09 May 2008**

This is the initial firmware release for the following printer models:

- HC100

## New Features

New implementation to support new printer models.

- Supports ZPL II, XML, and ZBI 2.0
- Supports internal wired and wireless printing
- New SetGetDo commands\*

\* See the current ZPL Programming Guide for a complete list of the new commands. The ZPL Programming Guide is available for download from <http://www.zebra.com/manuals>.

Table 1 lists the security types that are supported by the Internal Wireless Plus Print Server.

**Table 1 • Security Types Supported on the Internal Wireless Plus Print Server**

Security Type	Supported?	Security Type	Supported?
Open	Yes	WPA- EAP-FAST	Yes
EAP-FAST	Yes	WPA- EAP-TLS	Yes
EAP-TLS	Yes	WPA- EAP-TTLS	Yes
EAP-TTLS	Yes	WPA- PEAP	Yes
Kerberos	Not Supported	WPA2 - LEAP	Yes
LEAP	Yes	WPA2 - PSK	Yes
PEAP	Yes	WPA2- EAP-FAST	Yes
WEP (40 bit and 128 bit)	Yes	WPA2- EAP-TLS	Yes
WPA - LEAP	Yes	WPA2- EAP-TTLS	Yes
WPA - PSK	Yes	WPA2- PEAP	Yes

## Wireless Notes

The following items are issues Zebra has noted during testing with various wireless networking products:

- It is recommended to set WPA Handshaking to 1000.
- It is recommended to disable the Aironet Extensions.
- It is recommended to use Cisco Access Point firmware 12.3(8)JAE1 or later.

For support, please visit [www.zebra.com/support](http://www.zebra.com/support) or refer to the contact options below:

Geographic Location	Telephone	Toll-free	FAX
<b>The Americas</b>	+1-847-955-2299	+1-877-ASK-ZEBRA	—
<b>Asia Pacific</b>	+65-6858-0722	—	+65 6885 0838
<b>Europe, Africa, Middle East, India</b>	Please contact your supplier.		