



## Xplore Technologies Software Release Note

|                            |  |
|----------------------------|--|
| Name                       | <b>Intel Bluetooth Driver</b>                |
| File Name                  | <b>Intel_Bluetooth_Win8.1_20.110.0.3.zip</b> |
| Release Date               | March 20, 2019                               |
| This Version               | 20.110.0.3                                   |
| Replaces Version           | All previous versions                        |
| Intended Product           | Bobcat, CL920, C5m/F5m, R12, XSLATE B10, XC6 |
| File Size                  | 16 MB  |
| Supported Operating System | Windows 10 (64-bit)                          |

### Fixes in this Release

- Resolution for Security vulnerability INTEL-SA-00128

### What's New in this Release

- N/A

### Installation and Configuration Instructions

**To install the Bluetooth Driver 20.110.0.3 update, perform the following steps:**

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (setup.exe) and follow the prompts.
4. The update process may take some time. Do not manually power off the tablet during the update.

### Licensing

Refer to your applicable end-user licensing agreement for usage terms.