



Xplore Technologies Software Release Note

Name	Sierra Wireless Skylight Connection Manager
File Name	Sierra_Wireless_Skylight_W7W10_64bit%206.0.4378.7805_B4378.zip
Release Date	March 15, 2016
This Version	6.0.4378.7805 (B4378)
Replaces Version	All previous versions
Intended Users	Motion CL920, R12, and C5m/F5m users
Intended Product	Motion CL920, R12, and C5m/F5m Tablet PCs ONLY
File Size	35 MB
Supported Operating System	Windows 7, Windows 8.x, Windows 10 (32-64-bit)

Fixes in this Release

- Auto-connect GUI
- SIM detection after removal/re-insertion
- Support Profiles with user names longer than 32 characters
- Firmware version reporting

What's New In This Release

- None

Known Issues and Limitations

- None

Installation and Configuration Instructions

To install Wireless drivers, perform the following steps:

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (.exe) and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.