Release Notes – SPR 25326 – ET1N0 USB OTG Port gets no response when unplugging/plugging AC power (220V) several times.

Introduction

Description

Contents Device Compatibility

Installation Requirements Installation Instructions

Part Number and Release Date

Introduction

ET1N0 USB OTG Port gets no response when unplugging/plugging AC power (220V) several times.

Description

ET1NO USB OTG Port gets no response when unplugging/plugging AC power (220V) several times. Coming patch will fix the issue. When the issue happens, the Left-Top icon will disappear for 1~3 seconds. Please wait the icon to be displayed, and then the scanner should work again.

Contents

ET1 JB LAN Patch Fix TNT issue 04112014.zip

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Ì	Device	Operating System
	ET1N0	JB 4.1.1

Installation Requirements

Installation Instructions

- Copy ET1_JB_LAN_Patch_Fix_TNT_issue_04112014.zip to the root directory of SD card
- Place the SD card in the device to be upgraded and connect to A/C power
- 3. Press and hold the Power button on the device until the Device options menu appears
- Tap on Reset to reboot the device
- When the device is rebooting hold the right Scan/Action button to enter Recovery update mode
- When the Recovery Mode screen appears release the Right Scan/Action button.
- Tap Home Key to access recovery menu screen Tap P1, P2 keys to navigate to "apply update from /sdcard" option
- Tap P3 to select this option
- 10. Tap P1, P2 keys to navigate to ET1_JB_LAN_Patch_Fix_TNT_issue_04112014.zip file
- 11. Tap P3 to select this option
- 12. After pressing P3, the upgrade will start.
- After upgrading successfully, the screen will back to Recovery mode menu 13.
- 14. Tap P1, P2 keys to navigate to the "reboot system now" option
- 15. Tap P3 to select this option
- After pressing P3 system will reboot

Part Number and Release Date

May, 2014.