
Release Notes – ET1N0/N2 - Loses the "MTP/Camera" sync setting when going into critical battery suspend- SPR25216

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Instruction](#)

[Part Number and Release Date](#)

1 Introduction

ET1N0/N2 loses the "MTP/Camera" sync setting when going into critical battery suspend.

2 Description

ET1N0/N2 loses the "MTP/Camera" sync setting when going into critical battery suspend

3 Contents

1. SPR25216_0212_JB_WAN_REL_FullPackageUpdate.zip
2. SPR25216_0212_JB_LAN_REL_FullPackageUpdate.zip

4 Device Compatibility

This software release has been approved for use with the following Motorola devices.

Device	Operating System
ET1N0/N2	JB 4.1.1

5 Installation Instructions

1. Copy the patch to the root directory of SD card
2. Place the SD card in the device to be upgraded and connect to A/C power
3. Press and hold the Power button on the device until the Device options menu appears
4. Tap on Reset to reboot the device
5. When the device is rebooting hold the right Scan/Action button to enter Recovery update mode
6. When the Recovery Mode screen appears release the Right Scan/Action button.
7. Tap Home Key to access recovery menu screen
8. Tap P1, P2 keys to navigate to “apply update from /sdcard” option
9. Tap P3 to select this option
10. Tap P1, P2 keys to navigate to patch
11. Tap P3 to select this option
12. After pressing P3, the upgrade will start.
13. After upgrading successfully, the screen will back to Recovery mode menu

14. Tap P1, P2 keys to navigate to the “reboot system now” option
15. Tap P3 to select this option
16. After pressing P3 system will reboot

6 Part Number and Release Date

July, 2014