XPLORE
TECHNOLOGIES

Xplore Technologies Software Release Note

Name	**DisplayLink Dock Software**
File Name	**DisplayLink_7.9M5.zip**
Release Date	May 9, 2016
This Version	7.9 M5
Replaces Version	All previous versions
Intended Product	iX101B1 (Bobcat)
File Size	22.4 MB
Supported Operating System	Windows 7 Windows 8.1 Windows 10

Fixes in this Release

- On some configurations, the system configuration may repeat even after reboot.
- Blue screen with TDR failure when changing mode/resolution on Windows 10.
- Mouse pointer flashing on some adapters/docking stations with Windows 10.
- Screen swapping or blinking when connecting an external monitor which was previously used on primary graphics card on Windows 10.
- Citrix VDA from Citrix version 7.6 was not supported.
- DisplayLinkUserAgent.exe can generate abnormal CPU load.
- Some Windows 10 configuration may get a blue screen with TDR failure while docking or undocking.
- Monitor hotplug was not always detected when in low power mode.

What's New in this Release

- N/A

Known Issues and Limitations

- N/A

Installation and Configuration Instructions

To install DisplayLink 7.9M5, perform the following steps:
1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (DisplayLink_7.9M5.exe) and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.