Release Notes - MC40N0 Android JB - BSP v061016 - HotFix CFE v00.01 Package

Introduction

HotFix CFE (Cumulative Fixes from Engineering) Package contains multiple SPR Hotfixes into a single package. The HotFix CFE Package helps the end users to keep up to date with all the SPR Hotfixes for given product software release / revision.

HotFix CFE packages are validated only by engineering validation team and the package follows Zebra Technologies HotFix Package Policy. Click here to view HotFix Package Policy. HotFix Support Policy

Component Description and Version

Component / Description	Version
Product Build Number	00-4AJ11-J-0000-0000-00-M1-033017
Android Version	JB 4.1.1
Linux Kernel	3.0.31
Android SDK Level	19
Platform (TI/MPA/ etc)	TI - OMAP 4430 - 4AJ11
Bluetooth Stack	4
Partition Table	NA
Flash Size	4 GB

RAM Size	1 GB
MSP Package	7.08.67
Scanning Framework	3.1.11
DataWedge	3.1.36
Handwriting Recognition	NA
Moto Value Add (WR Components)	3.5.1-1
RxLogger	2.0.0.50
WiFi (TI)	A_3.01.0.0.055
GPS	NA
PTT	3.1.20
EA	2.53
SPAM	4.7 (MV)
SE965 Phase I firmware	PAABPS00-001-R03
SE965 Phase II firmware	No firmware update required
SE4750 Firmware	CAABVS00-001-R01D0
MobiControl Stage	11.2.0.1143

Fixes Included:

Fixes:

The CFE package **CFE-MC40N0-J-V0-061016-N-00-01.zip** file includes the following HotFixes:

SPR31851**-** Fixed an issue wherein Fusion sometimes returns the same RSSI values for all the Access Points having a particular SSID when queried

SPR31213 - Fixed and issue wherein the VoIP client was failed to register into PBX after the latest JB ugrade.

Package Details

CFE-MC40N0-J-V0-061016-N-00-01.zip

Device Compatibility

This HotFix CFE Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC40N0	Android JB Version 4.1.1	v061016

Installation Requirements

This SW patch is intended for the MC40N0 JB NonGMS devices running on v061016 build versions only

Installation Instructions

1. Connect the USB cable from your PC to the device.

2. Make sure MTP mode is selected in the USB settings in the device and MTP drivers are installed
   in your PC.

3. The internal SD card of MC40 will be seen in your PC as mounted drive MC40N0.

4. Copy the "**CFE-MC40N0-J-V0-061016-N-00-01.zip**" file to the root folder on internal SD
   card.

5. Press and hold the Power button on the device until the device options menu appears.

6. Tap on Reset to reboot the device.

7. When the device is rebooting hold the left Scan/Action button to enter Recovery update mode.

8. When the Recovery Mode home screen (Android logo) appears then release the left Scan/Action
   button.

9. Touch Home button to enter Recovery menu screen.

10. Click on Vol+ or Vol to navigate to the "apply update from sdcard" option.

11. Click on PTT key to select the option.

12. Click on Vol+ or Vol to navigate to the "**CFE-MC40N0-J-V0-061016-N-00-01.zip**" file.

13. Click on PTT key to select the "CFE-MC40N0-J-V0-061016-N-00-01.zip" file.

14. Click on Vol+ or Vol to navigate "reboot system now" and Click on PTT key to reboot the
   device.

Note: battery must have at least 30% charge for the update to proceed.

Release Date

July, 2017