



## Motion Computing Software Release Note

Name	<b>Intel WLAN Vista</b>
File Name	<b>Intel_WLAN_Vista_13.2.0.30.zip</b>
Release Date	July 13, 2010
This Version	13.2.0.30
Replaces Version	All previous versions
Intended Users	<b>LE1700, C5/F5, J3400, C5v/F5v, J3500</b>
Intended Product	LE1700, C5/F5, J3400, C5v/F5v, J3500 Tablet PCs ONLY
File Size	35 MB
Supported Operating System	<ul style="list-style-type: none"><li>Windows Vista (all versions except Windows Vista Home Basic)</li></ul>

### Fixes in this Release

- Incorrect roaming (C5v/F5v, J3500)
- Cisco CCKM issues after authentication timeout (C5v/F5v, J3500)

### What's New In This Release

- None

### Known Issues and Limitations

- 3945 adapter intermittently hangs when in PSP3 mode. Symptoms include connection loss, empty scan list, and 5005/5007/5032 event IDs in the Windows System Event log. Recommend driver version 12.4.4.5.

### Installation and Configuration Instructions

To install this version update, perform the following steps:

1. Download **Intel\_WLAN\_Vista\_13.2.0.30.zip**
2. Select your Tablet model and corresponding operating system
3. In the **Wireless Driver** section, click **Intel WLAN Vista vxxxxx**.
4. In the File Download window, click **Save** to download the Intel WLAN Vista vxx.x.x.x file (Intel\_WLAN\_Vista\_vxxxxx.zip) to the directory of your choice.
5. Unzip the file to a location on your local drive.
6. Double-click **Setup.exe** in the Install folder and follow the prompts.

### Licensing

Refer to your applicable end-user licensing agreement for usage terms.