

Release Notes - TC55 JB Rev A - “Dutch Dictionary is missing” – SPR26696

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

SPR26696 - TC55 JB -Dutch Dictionary is missing

Description

When Language and Spellchecker are both set to Dutch the Dictionary is missing. Device doesn't succeed to spell check the words.

Contents

SPR26696_TC55_JB_en_1.74.99.17_v1_0_GMS.zip - OTA package for GMS device

SPR26696_TC55_JB_en_1.74.99.17_v1_0_nGMS.zip - OTA package for non-GMS device

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
TC55	Android 4.1.2 JB 1.74.99.17

Installation Requirements

This SW is intended for the TC55 device running non-GMS/GMS 01.74.99.17 build only

Installation Instructions

OS Recovery Update

Connect the USB cable from your PC to the device and enable USB mass storage mode on the device.

On your PC you should see an internal and external USB mass storage drive (SD card) appears in the File Explore and copy the recovery update zip file to any storage.

Press and hold on the device the Power button, Scan/Action button and Vol+ until the screen is turned OFF

Release the Power and Scan/Action buttons and continue to hold Vol+ button

The device should enter to Recovery update mode

Release Vol+.

Click on Vol+ or Vol- to navigate and select appropriated storage

Click on on Scan/Action button to select the option

Click on Vol+ or Vol- to navigate to the recovery update zip file

Click on on Scan/Action button to select the recovery update zip file

Device will automatically reboot and will be ready to use.

Part Number and Release Date

February, 2014