

Windows 10 Image Inventory [ RTL10 Product Line]	
Software Component	L10AX-WIN10PRO-063023_Z01_BSP
<b>Supported Models</b>	<b>RTL10C0, RTL10C1</b>
Windows 11 Supported Versions*	21H2-22H2
Windows 11 Supported Builds*	10.0.19044, 10.0.19045
<b>Inf Install Drivers</b>	<b>Version</b>
Intel Chipset Driver (Tiger Lake)	10.1.24.6 / 10.1.43.5
Intel Dynamic Tuning Technology	8.7.10700.22502
Intel GNA Scoring Accelerator module	03.00.00.1457
Intel HID Event Filter	2.2.1.386
Intel Management Engine Interface	2251.4.2.0
Intel Serial IO (GPIO, I2C, SPI, UART)	30.100.2129.8
Intel Smart Sound Technology	10.29.0.8102
Intel Wireless Bluetooth	22.200.0.2
Intel Wi-Fi 6E AX210 160 MHz	22.220.0.4
Intel Ethernet Connection I219-M	12.19.2.45
Intel TGL AVStream Camera (IPU)	60.22000.6.6634
L10 PCButtons Device	4.7.0.2
NxpNfcClient Driver	12.0.6.0
Rear Camera Sensor AR1337 (IPU)	60.22000.6634.2
Synaptics Fingerprint	6.0.10.1122
ASIX AX88179 USB 3.0 to Gigabit Ethernet Adapter	(in-box)
<b>Silent Install Drivers</b>	
Intel Irtis Xe Graphics	31.0.101.4502
Realtek High Definition Audio Driver - ALC888	6.0.9244.1
Intel Integrated Sensor Solution	3.1.0.4477
[RTL10C1 Model Only] Quectel RM505-5G WWAN WWAN Carrier Firmware:	2.0.0.8(pkg)
• Default: RM505QAEAAAR11A03M4G_03.004	
• Verizon: RM505QAEAAAR11A04M4G_03.001	
Quectel PCI Express	1.0.0.13
Generic Mobile Broadband Adapter	(in-box)
Quectel Wireless Location Sensor	1.0.0.4
Quectel QMUX Interconnect	1.0.0.6
Quectel UDE Device	1.0.0.13
HighSpeed USB Composite Device(UDE)	30.0.0.0
O2Micro OZ776 SCR Driver (if CAC present)	2.11.4.256
DisplayLink Graphics Driver (Dock)	11.0.2412.0
PL-2303 USB-to-Serial (Dock)	2.0.2
<b>Silent Install Applications</b>	

Camera Init Set Service	1.0.2
RTL10 Touch Mode	1.3.0
xKnowTab (Know Your Tablet)	3.6.5
Zebra Workforce Connect PTT Client	3.0.0.15044
xSysMon (System Monitor)	02.02.0005

Note \* : Microsoft Deployment Toolkit (MDT) build was successfully run for all Windows 10 OS revisions starting from Windows version 21H2 to 22H2.