



## Motion Computing Software Release Note

Name	<b>Intel Bluetooth 4.0 Driver</b>
File Name	<b>Intel_Bluetooth_64bit_17.1.1411.01.zip</b>
Release Date	February 10, 2015
This Version	17.1.1411.0506
Replaces Version	All previous versions
Intended Users	<b>Motion Computing CL920, R12, C5te and F5te users</b>
Intended Product	Motion Computing CL920, R12, C5te and F5te Tablet PCs only
File Size	33 MB
Supported Operating System	Windows 8.1 (64-bit)

### Fixes in this Release

- Music buffer management
- Mouse reconnect after distance disconnect
- HFP audio following power management events
- Uninstall/repair/upgrade hang

### What's New In This Release

- None

### Known Issues and Limitations

- None

### Installation and Configuration Instructions

**To install Bluetooth 4.0 drivers, perform the following steps:**

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (setup.exe) and follow the prompts.

### Licensing

Refer to your applicable end-user licensing agreement for usage terms.