×	PL	_0	R	
TECHNOLOGIES				

# Motion Computing Software Release Note

### Name Motion Connection Manager for Windows 7

### File Name MotionCMSetup3020404.zip

Release Date October 14, 2013

This 3.2.4.4

Replaces All previous versions for Sierra Wireless MC8355 module Version (Gobi 3000)

Intended Motion CL900/CL910, C5v/F5v, C5t/F5t, C5te/F5te, Users J3500 and J3600 users with MC8355 modules installed

Intended Motion CL900/CL910, C5v/F5v, C5t/F5t, C5te/F5te, Product J3500 and J3600 Tablet PCs with MC8355 ONLY

File Size 11 MB

Supported

Operating Windows Vista, Windows 7 System

### Fixes in this Release

• Fixed a problem with the MotionCM SDK when running on 64-bit Windows versions.

### What's New In This Release

 Users may now have APN passwords encrypted so they will not appear in the Profiles.txt file in clear text. To encrypt an APN password, use the MotionCM Networks page to modify or create the profile and surround the password with brackets. For example, to encrypt "MyPassword", enter it as "[MyPassword]". The resulting password entry that is stored in the file will be encrypted except for the brackets, which will remain readable.

Known Issues and Limitations

- This version will only install on Motion Computing Tablet PCs with the Sierra Wireless MC8355 (Gobi 3000) module.
- The MotionCM installer keeps intact any existing Profiles.txt and Carriers.txt configuration files. If you want to install the latest versions of these files and have no need to preserve the older files, you must first manually delete the existing files from C:\MotionCM.

# Installation and Configuration Instructions

## To install Motion CM 3.2.4.4, perform the following steps:

- 1. Download the update and save to the directory location of your choice.
- 2. Unzip the file to a location on your local drive.
- 3. Double-click the installer (MotionCMSetup3020404.msi) and follow the prompts.

#### Licensing

Refer to your applicable end-user licensing agreement for usage terms.